W

OUT60381

13 TOV 15 OI 10 T

P 150107Z NOV 66
FM NPIC WASHDC
TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUCVAAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 9045.

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)
2D AF (FOR DI).

- 1. CAMERA B 15 WAS USED IN MISSION G 925 FLOWN ON 12 NOVEMBER 1966. PROCESSING WAS ACCOMPLISHED AT BARKSDALE.
 - 2. ORIGINAL NEGATIVE

A. THE DENSITY OF THE MATERIAL IS NORMAL AND THE RESOLUTION IS GOOD.

B. 9R SIDE: EDGE STATIC IS PRESENT ALONG BOTH EDGES OF THEFILM THROUGHOUT THE MISSION. A ROW OF MINUS DENSITY DOTS LOCATED

1.0" FROM THE INBOARD EDGE AND 1.7" APART ARE PRESENT THROUGHOUT

VERY MINOR ROLLER CHATTER WAS ALSO NOTED ALONG THE INBOARD EDGE.

IN SEVERAL VERTICAL FRAMES THERE IS A VERY SLIGHT CHANGE IN

DENSITY APPROXIMATELY 3.0" FROM THE DATA BLOCK. IT IS PROBABLY

CAUSED BY EITHER A REFLECTION IN THE WINDOW OR AN INTERNAL CAMERA

REFLECTION. THIS ANOMALY HAS BEEN REPORTED BEFORE.

C. 9L SIDE: EDGE STATIC WAS NOTED ALONG BOTH SIDES OF THE MATERIAL. THERE IS ALSO SLIGHT FOGGING INTO THE FORMAT CAUSED BY

DISTRIBUTION Office Action Gr Ra. SEC BE TOS CSD IPD PD PSD PSD-ICB TIN IAD PAG DIAXX-C SPAD HSA-LO DIA-AP Advance conv

1 5 NOV 1855

Saniliz**ed**

-2-

THE VERTICAL DOT INDICATOR. IT DOES NOT NOTICEABLY DEGRADE THE IMAGERY AND CAN BE SEEN ONLY OVER LOW DENSITY AREAS SUCH AS WATER.

- D. BOTH SIDES: THERE WERE A FEW FRAMES NOTED THROUGHOUT THE MISSION THAT WERE SMEARED. THE CAUSE PROBABLY CAN BE ATTRIBUTED TO VEHICLE MANEUVERS. THE LAST TITLED FRAME WAS 2344.
 - 3. POSITIVE
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING IS GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 35 PERCENT OF THE MISSION.

GP-1

SECRET

-- END OF MESSAGE --